

August 30, 2021

Board of Selectmen
Town Of Warren
48 High Street
Warren MA 01083

Re: Old Town Hall Building – Structural Assessment
1 Milton O Fountain Way
Warren MA 01083

Attn: David Dufresne, Chairman

Dear David,

This letter is a structural assessment of the Old Town Hall building located at 1 Milton O Fountain Way and addresses the Foundation, Masonry Walls, Floors, Roof and the Clock Tower. Attached to this letter are captioned photos, cost estimates for the building renovation per current code to the former use group of each floor, being Business use on the first floor and Assembly use for the public on the second floor, as requested an estimate for the demolition of the building is included on the last page.

Structural Assessment:

1. Building Foundation: The building foundation which measures 115' x 56' outside is constructed of stone rubble and/or brick mortared in place, interior structural piers are also of stone rubble and/or brick. No failure of the foundation system was observed however the bottom 24" +/- of brick above the basement floor needs re-pointing and some brick replacement, most likely due to continual historical flooding of the basement during high flow conditions of the Powder Mill Brook that flows against the foundation on the South side of the building. There is evidence of multiple areas where the foundation leaks water currently causing high humidity and mold issues. One dehumidifier was observed but cannot keep up with the water entering the basement due to the permeability of the foundation. Except for the above issues the foundation is in good condition but needs reinforcement for seismic upgrades. Recommended seismic upgrades to include the replacement of the deteriorated brick columns with concrete filled steel columns, a reinforced concrete floor and buttress walls for the exterior rubble stone and brick foundation walls.

305 WHITNEY STREET
LEOMINSTER, MA 01453
www.MCKENZIEINC.COM
(978) 537-8210

2. Masonry Walls: The exterior walls of the building on the East, North and West sides are faced with a yellow beige hard burned face brick with narrow joints that was added to the building after the 1900 fire. The South (rear) side of the original building is faced with a softer red brick. The majority of the brick surface on the building is in good condition with the following deficiencies noted:
 - a. The brick on the North (Main Street) side from the Northeast corner at the Clock Tower is cracked/broken in many places and in need of repair. Refer to attached photo's #2811 thru 2814 showing various types of damage to the existing brick work requiring reconstruction. Additionally, the three facades with the yellow beige hard burned brick are stained/soiled and in need of cleaning and re-pointing as required.
 - b. On the South (Powder Mill Brook) side there are deteriorated original red brick joints that need repointing. The Southwest area beyond the chimney also needs repointing work. The brick joint between the original building and the Memorial Hall addition requires new caulking. Access to this side of the building is difficult and trees, brush and vines growing up the brick would need to be cut to allow this proposed work.
 - c. The limestone columns at the main entrance Portico are in reasonably good shape with some joints requiring repointing. The Portico limestone should be cleaned as should all the face brick on the building. It was noted that the wood roof deck of the portico is rotted and should be replaced.
3. Floors: From the basement the first-floor joist measurements and clear unsupported spans varied however in general they were measured as 1 ¾"x11 ¼" wood joists at 16" o.c. spanning 23', using a bending stress of 1400 psi with a 1.15 repetitive member factor and a dead load of 15 psf gives a live load rating of 60 psf which is sufficient for normal business use. The second-floor joist sizes per a Nov. 23, 2010 letter by Engineering Design Associates, Inc. were measured as 1 ¾" x 13" at 12" o.c. and as 2 ¾" x 13 ½" at 16" o.c., both spanning 24'-4" between bearing walls, using again 1400 psi allowable bending stress, a 1.15 repetitive member factor and a 15 psf dead load gives a live load rating of 74 psf and 99 psf respectively. Note that the minimum live load rating for assembly use is 100 psf. Per these live load calculations some reinforcement of the second-floor framing would need to be done for a proposed assembly use. The first floor level of the west addition was constructed 42" below the level of the original building first floor level, and an additional "mezzanine level" floor was constructed between the first and second floors. Headroom clearance does not meet code in this mezzanine level and this level is nonfunctional. I would recommend that the west addition first floor be brought level with the original building floor and the mezzanine level floor be eliminated.

4. Roof: The roof is conventionally framed with onsite constructed trusses to clear span over the auditorium. The top chord of the truss cantilevers approximately 4' from the bearing points on the North and South exterior walls to the bottom chord connection point. This cantilever creates an overstressed condition with a code snow load in the top chord and requires the trusses to be reinforced. The balcony and stairs to the balcony are also hung from what appears to be a 5-gang truss which cannot support a code required live load for the balcony of 100 pounds per square foot (psf). Truss reinforcement for the proper loads from the balcony support rods is required in my opinion. The upper low slope/flat roof area appears to have a relatively new TPO or PVC membrane and is in good condition. This upper low slope roof drains to a higher slope slate shingled roof that was observed to need some maintenance and repair of damaged/dislodged slates. The roof eaves have built in copper gutters which discharge to copper downspouts that drain to cast iron piping in the basement that drains to the powder mill brook on the South side. The gutters, fascia and soffit could only be observed from the ground but appear to be in good condition with the exception of some wood trim replacement and scraping and painting. There most likely is some copper replacement that will be required also which is typical for buildings of this age.
5. Clock Tower: The clock tower which measures 14' +/- square is constructed of unreinforced red brick with an exterior wythe of the yellow beige hard burned brick. The upper open level where the bell is located is wood framed with a copper roof and a copper floor at the bell level. It was observed that the bell level copper floor is leaking and that some wood trim and potentially framing at that level is rotting due to lack of maintenance and age. The copper upper roof could not be accessed but visually appears to be in good condition. Access to the bell level is difficult at best and extremely constricted. As previously mentioned under masonry, repairs to cracked and broken bricks in the clock tower will be required. The clock tower may make a good location for an elevator shaft.

Attached to this report as requested is a cost estimate to bring the first and second floors up to current code so that the entire building can be used with the second-floor auditorium being returned to an assembly use group. Costs included in the estimate to accomplish this upgrade include the foundation upgrades described, gutting the building, removal of the chimney, retrofitting of the west addition first-floor level, elimination of the mezzanine level, new stairs and windows in the west addition, upgrades on both levels and roof to meet current energy code, retrofitting for accessibility including an elevator retrofit in the clock tower shaft, new electrical, bathrooms, plumbing and HVAC. Structural upgrades and repairs to the foundation, exterior brick including seismic upgrades, windows, fascia, soffit, second floor framing and roof are also included as are a fire alarm and sprinkler system.

Please call if you have any questions.

Very Truly Yours,



Peter M. Reynolds, P.E.
President

ME-4317\Str Assessment Old Town Hall 08-30-21

Email: Jim Dusty <maintenance@warren-ma.gov>, David Dufresne <dufresne@warren-ma.gov>

Old Town Hall - Warren MA, 1 Milton O Fountain Way



Fire Escape From Balcony - Poor Condition
IMG_2723



Powder Mill Brook Against Building- South Side
IMG_2719



IMG_2724



Red Soft Brick Facade - South Side
IMG_2722



Clock Tower
IMG_2727



South East Corner
IMG_2725



Portico - Rotted Wood Deck - East Side
IMG_2728



South East Corner
IMG_2726



Clock Tower
IMG_2731



Portico - East Side
IMG_2729



Base - Clock Tower North Side
IMG_2732



Base - Clock Tower East Side
IMG_2730



North (Main St - Rte 67)
IMG_2735




2 Electric Services - top one abandoned North (Main St - Rte 67) Side
IMG_2733



Rusted Architectural Columns - North (Main St - Rte 67)
IMG_2736



North (Main St - Rte 67)
IMG_2734



Police Entrance - North (Main St - Rte 67) Side
IMG_2739



North (Main St - Rte 67)
IMG_2737



Police Entrance - North (Main St - Rte 67) Side
IMG_2740



North (Main St - Rte 67)
IMG_2738



Settlement of Steps - West Side
IMG_2743



Bulkhead - Generator - West Side
IMG_2741



Typical Replacement Window -
Wood Head, Jambs and Sill



West Side
IMG_2742



Dehumidifier - Rubble Stone and Brick Piers
IMG_2748



Rubble Stone and Brick Foundation
IMG_2746



Historical Fire Damage
IMG_2749



Rubble Stone and Brick Foundation - Basement Door South Side
IMG_2747




Basement - Brick Arch - Unknown Use
IMG_2752



Brick Deterioration
IMG_2750



Brick Deterioration
IMG_2753



Poor Wiring Methods
IMG_2751



Knob & Tube Wiring - Typical Throughout
IMG_2756



Current Gas Boiler for 1st Floor
IMG_2754



First Floor Joist Additional Support Beams
IMG_2757



Brick Deterioration
IMG_2755



Small 1" Water Service

IMG_2760



Rust Deterioration
of Steel Basement
Columns

IMG_2758



IMG_2761



Basement - Dirt & Concrete floors

IMG_2759



Poor Joist To Beam Attachment

Basement - Joist Attachment - Moisture/Mold Many Areas

IMG_2764



Basement - Heat Pump Condenser

IMG_2762



Basement - Variety of Wiring Methods
None would meet a proposed Assembly Use

IMG_2765



Basement - Beam Deflection

IMG_2763



Basement - Water Infiltration Through Walls and SLab

IMG_2768



Basement - Moisture Damage to Framing

IMG_2766



Abandoned Air Handler

IMG_2769



Knob & Tube Wiring - Typical Throughout


IMG_2767



Steam Piping System - Basement - Damage to Fireproofing of Framing
IMG_2772



Misc Piping
IMG_2770



First Floor Ceiling Detailing
IMG_2773



Wiring - Typical Brick Piers
IMG_2771



Stair @ NW Corner of Bldg
IMG_2776



West Wall - Memorial Hall -Weight Room
IMG_2774



Second Floor Hall - Balcony
IMG_2777




First Floor - Memorial Hall - Weight Room
IMG_2775



Second Floor Hall - Ceiling @ Balcony - Ladder to Attic

IMG_2780



Second Floor Hall - Stage

IMG_2778




Second Floor Hall - Balcony

IMG_2781



Second Floor Hall - Stairs to Balcony

IMG_2779



In Clock Tower - Bell Level Deck Above
IMG_2785




In Clock Tower
IMG_2782



Clock Tower Masonry Walls

In Attic
IMG_2786



In Clock Tower @ Clock Level
IMG_2784



Center Flat Roof Area

IMG_2789



Ventilation Ductwork in Attic

IMG_2787



Broken/Rotted Wood

Clock Tower - Bell Level

IMG_2790



Typical Attic Framing - No Fire Protection

IMG_2788



Ventilating Cupola
IMG_2793



Clock Tower - Bell Level
IMG_2791



100+ year old Slate
Roof & Snow Guards

IMG_2794



Poor Condition
needs re-pointing
and new brick

IMG_2792



NW Corner of Roof
IMG_2797



IMG_2795

Slate Shingle Damage



NE Corner of Roof
IMG_2798



SE Corner of Roof
IMG_2796



Rotted Wood Balustrades
at Bell Area

IMG_2801




Ventilation Cover - Obsolete

IMG_2799



Water damaged Ceiling
Below Clock Tower

IMG_2802



Clock Tower Flashing

IMG_2800



Roof Framing Over Rear of Stage
IMG_2805



IMG_2803



Rotted Deck - Portico
IMG_2806




2nd Floor - Balcony Looking Toward Stage - Front Wall
IMG_2804



Brick Damage - East Side Entrance

IMG_2809



IMG_2807



Insect Damage to Wood

IMG_2810



Rotted Deck - Portico

IMG_2808



IMG_2813



IMG_2811



IMG_2814



IMG_2812

McKENZIE ENGINEERING CO., INC.
305 WHITNEY STREET, LEOMINSTER MA 01453
(978) 537-8210

DATE: 08/30/2021

WORK DESCRIPTION: **RENOVATION TO CURRENT CODE**
1ST FLOOR BUSINESS USE GROUP
SECOND FLOOR ASSEMBLY USE GROUP
 BLDG = 115x56 = 6500 S.F./ FLOOR

JOB: **TOWN OF WARREN**
OLD TOWN HALL

#	WORK DESCRIPTION DESIGN COST - SEE TOTAL COST AT END OF ESTIMATE	# UNITS	UNIT COST	COST	
CONSTRUCTION					
1	DIV 01 — GENERAL CONDITIONS				
	MOBILIZATION & DEMOBILIZATION	1	35,000.00	35,000.00	
	G.C. 16 MO. @ 28,000/MO	16.0	28,000.00	448,000.00	
	BUILDING PERMIT	1.0	42,000.00	42,000.00	
	TEMP SERVICES FOR CONTR	1.0	10,000.00	10,000.00	Total 01 \$535,000.00
2	DIV 02 - DEMOLITION & SITE CONSTRUCTION				
	DEMOLITION & DEMO PREP				
	GUT INTERIOR OF BUILDING INCL ELEC AND PLUMBING 14500 S.F.	14,500.0	9.00	130,500.00	
	DEMO WEST ADDN FIRST AND MEZZ LEVEL FLOORS	3,200.0	6.00	19,200.00	
	CLOCK TOWER DEMO FOR ELEV SHAFT	1.0	9,500.00	9,500.00	
	BASEMENT FLOOR DEMO FOR NEW REINF CONC FLOOR	6,500.0	5.00	32,500.00	
	BASEMENT PIER DEMO	1.0	7,600.00	7,600.00	
	DEMO PORTICO ROOF AND WOOD ROOF DECK FOR REPLACEMENT	1.0	6,000.00	6,000.00	
	DEMO EXISTING VENT DUCTS AND ROOF VENTING STRUCTURES	1.0	15,000.00	15,000.00	
	DEMO PIT & OPENINGS IN CLOCK TOWER SHAFT FOR NEW ELEVATOR	1.0	35,000.00	35,000.00	
2B	SITework				
	EXCAVATION AND INSTALL NEW PERIMETER BASEMENT DRAIN AND SUMP W/PUMP	1.0	35,000.00	35,000.00	
	EXCAVATION FOR NEW REINF CONC BASEMENT FLOOR	1.0	35,000.00	35,000.00	
	HC PARKING SPACE COSTS	1.0	1,500.00	1,500.00	
	MISC TEMP FENCING	1.0	7,500.00	7,500.00	
	EXCAV FOR ACCESSIBLE RAMPS	1.0	6,500.00	6,500.00	
	SPR & WATER TAPPING FEE (NOT INCLUDED)	1.0	0.00	0.00	
	SPRINKLER AND WATER SERVICES INTO BUILDING	1.0	45,000.00	45,000.00	
	PIPE BOLLARDS (10)	1.0	24,000.00	24,000.00	
		10.0	1,500.00	15,000.00	Total 02 & 2I \$424,800.00
3	DIV 03 - CONCRETE				
	FOOTINGS FOR NEW CONCRETE COLUMNS AT EXISTING BRICK PIERS	1.0	38,000.00	38,000.00	
	4" REINF CONCRETE FLOOR BASEMENT	6,500.0	14.00	91,000.00	
	4" REINF CONC FLOOR FIRST AND SECOND FLOORS	3,000.0	14.00	42,000.00	
	BUTTRESS WALLS TO FNDN (6)	6.0	5,200.00	31,200.00	
	ELEVATOR PIT FLOOR & WALLS @ EXISTING CLOCK TOWER	1.0	25,000.00	25,000.00	
	ACCESSIBLE RAMPS EAST AND WEST SIDES	2.0	88,000.00	176,000.00	
		1.0	72,000.00	72,000.00	Total 03 \$475,200.00
4	DIV 04 - MASONRY				
	BRICK CLEANING , SOAP SCUB AND PRESSURE WASH 10000 S.F.	10,000.0	5.00	50,000.00	
	BRICK REPLACEMENT, 100	100.0	150.00	15,000.00	
	BRICK RE-POINTING, 4,000 L.F.	4,000.0	7.00	28,000.00	
	SEISMIC REINFORCING WITH STEEL FROM INTERIOR	10,000.0	35.00	350,000.00	Total 04 \$443,000.00
5	DIV 05 - METALS				
	STR STEEL, JOISTS & METAL DECK - NEW FLOORS WEST ADDN - 10 TON	10.0	9,500.00	95,000.00	
	MISC METALS - INTERIOR STAIRS AND RAILINGS	1.0	48,000.00	48,000.00	
	RAILINGS FOR 2 RAMPS	180.0	110.00	19,800.00	
	ROOF STRUCTURE FOR RAMPS	2.0	150,000.00	300,000.00	Total 05 \$462,800.00
6	DIV 06 - CARPENTRY				
	STRUCRURAL UPGRADES TO ROOF, BALCONY SUPPORT	1.0	45,000.00	45,000.00	
	INT WALLS FRAMED - WOOD 17000 S.F.	17,000.0	12.00	204,000.00	
	GYP BD, WALLS AND CEILINGS	28,000.0	5.50	154,000.00	
	WOOD TRIM	3,500.0	10.00	35,000.00	
	MISC MODIFICATIONS TO ELEV SHAFT, OPENINGS, METAL STUD, GWB, DRYWALL	1.0	20,000.00	20,000.00	Total 06 \$458,000.00
7	DIV 07 - THERMAL & MOISTURE PROTECTION				
	INSUL	13,000.0	4.00	52,000.00	
	ROOFING - MEMBRANE PATCHING	500.0	17.00	8,500.00	
	PORTICO ROOF	400.0	17.00	6,800.00	Total 07 \$67,300.00
8	DIV 08 - DOORS & WINDOWS				
	EXT DOORS	6.0	6,500.00	39,000.00	
	NEW WINDOWS, EXISTING WOOD FRAMES REMOVED, NEW P.T. FRAMING, CAULKED	52.0	1,800.00	93,600.00	
	INT DOORS	32.0	2,100.00	67,200.00	
	INT WINDOWS	8.0	800.00	6,400.00	
	SECURITY SYSTEM AND DOOR COMPONENTS	1.0	27,000.00	27,000.00	Total 08 \$233,200.00
9	DIV 09 - FINISHES				
	ACOUSTICAL SUSPENDED CEILINGS	7,000.0	6.00	42,000.00	
	FRP WALLS IN BATHROOMS	3,500.0	6.00	21,000.00	
	FLOORING 1ST FLOOR	6,500.0	12.00	78,000.00	
	FLOORING 2ND FLOOR - HARDWOOD FINISHED, SEALED	5,000.0	18.00	90,000.00	
	PAINTING	42,000.0	2.30	96,600.00	Total 09 \$327,600.00
10	DIV 10 - SPECIALTIES				
	FIRE EXTINGUISHERS	7.0	80.00	560.00	Total 10 \$560.00
12	DIV 12 - FURNISHINGS				
	MISC CABINETRY & BATHROOM FURNISHINGS	6	6,500.00	39,000.00	Total 12 \$39,000.00
14	DIV 14 - CONVEYING SYSTEMS				
	ELEVATOR INSTALLED	1	195,000.00	195,000.00	Total 14 \$195,000.00

15	DIV 15 - MECHANICAL				
	PLUMBING FOR BATHROOMS, SINKS, 20 Fixtures	20	6,500.00	130,000.00	
	GAS PIPING	1	6,500.00	6,500.00	
	ROOFTOP GAS HEAT ELEC COOL, 4 UNITS 10 TON EACH WITH DUCTWOR TO 1ST & 2ND FLOORS	40	7,800.00	312,000.00	
	HRV SYSTEM	1	38,000.00	38,000.00	
	ROOF DRAINANGE SYSTEM REPAIR	1	4,000.00	4,000.00	
	SPRINKLER SYSTEM INSTALL, BSMT, 1ST, 2ND, ATTIC	26,000	4.75	123,500.00	Total 15 \$614,000.00
16	DIV 16 - ELECTRICAL				
	FIRE ALARM SYSTEM - NOTIFIER	1	21,000.00	21,000.00	
	NEW 400 A 3 PHASE SERVICE, MAIN PANEL	1	22,000.00	22,000.00	
	4 SUB PANELS, 200A EACH	4	6,200.00	24,800.00	
	LIGHTING INCL EMERG & EXITS	15,000	4.50	67,500.00	
	EXT LIGHTING	1	4,800.00	4,800.00	
	SECURITY WIRING FOR ACCESS DOOR CONTROLS	1	15,000.00	15,000.00	
	MISC DATA/TEL LINES	1	6,500.00	6,500.00	
	POWER & ELEVATOR WIRING	1	8,000.00	8,000.00	Total 16 \$169,600.00
17	ONGOING AND FINAL CLEAN UP	14	6,000.00	84,000.00	
	DISPOSAL - (15) 40 YD DUMPSTERS @ 2000	15	2,000.00	30,000.00	Total 17 \$114,000.00
	Total:			\$4,559,060.00	\$4,559,060.00

	TRADE TOTALS	\$	4,559,060.00
	Overhead & Profit % 15%	\$	683,859.00
	Safety (meetings, etc.)	\$	39,000.00
	Contingency 20%	\$	911,812.00
	TOTAL CONSTRUCTION COST:		\$6,193,731.00
	ARCHITECTURAL & ENGINEERING FEES 12%	\$	743,248.00
	TOTAL PROJECT COST:		\$7,887,791.00

McKENZIE
ENGINEERING
COMPANY, INC.

August 30, 2021

Board of Selectmen
Town Of Warren
48 High Street
Warren MA 01083

Re: Building Demolition Cost
Old Town Hall Building


Attn: David Dufresne, Chairman

Dear David,

To provide the town with an accurate cost of demolition for the Old Town Hall building I contacted Ray Bourgeois of Bourgeois Wrecking in Westminister MA. Ray inspected the site and gave me a price of \$250,000.00 assuming all asbestos related abatement had already been completed. I recommend you carry a price of \$300,000 for any price increases and for the filling of the basement with gravel and a stone/rip-rap finish.

Please call if you have any questions.

Very Truly Yours,



Peter M. Reynolds, P.E.
President

ME-4317\Building Demolition Cost - Old Town Hall 08-30-21

Email: Jim Dusty <maintenance@warren-ma.gov>, David Dufresne <dufresne@warren-ma.gov>

305 WHITNEY STREET
LEOMINSTER, MA 01453
www.MCKENZIEINC.COM
(978) 537-8210